


AL T-06 or AL T-12 CONNECTIONS WHEN THRU WIRING LUMINAIRE IS USED (T)



EXAMPLE OF PINS ON THE CONNECTOR. PLEASE CHECK CORRECT MARKINGS ON THE LUMINAIRE CONNECTOR.

